

AD-A156 681


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
CLARKVILLE POND DAM C. (U) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV MAR 81


1/1

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A


AD-A156 681

**QUINEBAUG RIVER BASIN  
GLOCESTER, RHODE ISLAND**

**CLARKVILLE POND DAM  
RI 01309**

**PHASE 1 INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM**

DTIC FILE COPY



**DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
WALTHAM, MASS.**

**MARCH 1981**

**DISTRIBUTION STATEMENT A**

Approved for public release  
Distribution Unlimited

85 6 28 111

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER RI 01309	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Clarkville Pond Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE March 1981
		13. NUMBER OF PAGES 53
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Quinebaug River Basin Glocester, Rhode Island Mary Brown Brook		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The dam is a stone wall earth embankment about 400 ft. long with a maximum height of 14 ft. The dam is considered to be in poor condition. To assure the long term performance of the dam, several items of concern require further attention. The dam is small in size with a high hazard potential. The test flood is $\frac{1}{2}$ the PMF. There are various remedial measures which must be undertaken by the owner.		



DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
424 TRAPELO ROAD  
WALTHAM, MASSACHUSETTS 02254

REPLY TO  
ATTENTION OF:

JUL 21 1981

NEDED


Honorable J. Joseph Garrahy  
Governor of the State of Rhode Island  
State House  
Providence, Rhode Island 02903

Dear Governor Garrahy:

Inclosed is a copy of the Clarkville Pond Dam (RI-01309) Phase I Inspection Report, prepared under the National Program for Inspection of Non-Federal Dams. This report is based upon a visual inspection, a review of past performance, and a preliminary hydrological analysis.

The visual inspection of Clarkville Pond Dam has revealed the dam to be in poor condition with seepage and structural problems that could affect its future performance. In addition the preliminary hydrologic analysis indicates that the spillway capacity would likely be exceeded by floods greater than 15 percent of the Probable Maximum Flood (PMF). Our screening criteria specifies that a dam classified as high hazard with a spillway capacity insufficient to discharge fifty percent of the PMF be judged as having a seriously inadequate spillway. Because of the concerns with the condition of the dam and the inadequacy of its spillway, the dam is assessed as unsafe until corrective measures are made.

We recommend that the owner immediately after receipt of this report engage the services of a qualified registered engineer in order to accomplish the recommendations in Section 7. Based on the engineers recommendations, appropriate remedial mitigating measures should be designed and completed within 12 months of this date of notification. In the interim, a detailed emergency operation plan and warning system should be promptly developed and round-the-clock surveillance be provided during periods of heavy precipitation or high project discharge.



Accession For	NTIS GRA&I	<input checked="" type="checkbox"/>
	DTIC TAB	<input type="checkbox"/>
	Unannounced	<input type="checkbox"/>
	Justification	
By		
Distribution/		
Availability Codes		

11

27

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DTIC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

WFFED-E

Honorable J. Joseph Garrahy

I approve the report and support the findings and recommendations described in Section 7, with qualifications as noted above. I request that you keep me informed of the actions taken to implement these recommendations since this follow-up is an important part of the program.

Copies of this report have been forwarded to the Department of Environmental Management and to the owner, Mr. John Abbott, Pawtucket, Rhode Island. Copies will be available to the public in thirty days.

I wish to thank you and the Department of Environmental Management for your cooperation in this program.

Sincerely,



C. E. EDGAR, III

Colonel, Corps of Engineers

Commander and Division Engineer


Incl

As stated

**QUINEBAUG RIVER BASIN  
GLOCESTER, RHODE ISLAND**

**CLARKVILLE POND DAM  
RI 01309**

**PHASE 1 INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM**



**DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
WALTHAM, MASS.**

**MARCH 1981**



# NATIONAL DAM INSPECTION PROGRAM

## PHASE I - INSPECTION REPORT

Identification No.: RI 01309  
Name of Dam: Clarkville Pond Dam  
Town: Glocester  
County and State: Providence, Rhode Island  
Stream: Mary Brown Brook  
Owner: John Abbott  
Date of Inspection: 14 November 1980

### BRIEF ASSESSMENT

Clarkville Pond Dam is a stone wall, earth embankment structure approximately 12 feet wide at the crest and 400 feet long. It has a maximum height of approximately 14 feet. The upstream slope is partially covered with riprap and on the downstream side of the dam there are two dry masonry walls, a 3 foot high knee wall and an 8 foot high stone wall.

The spillway, located near the left abutment, is approximately 30 feet long and consists of large stone slabs set as steps on the downstream side. The two training walls are of reinforced concrete placed against an earlier dry masonry wall. There are no outlet works other than a high level power canal intake, which is no longer operable.

The dam was constructed on Mary Brown Brook, within the Quinebaug River Basin and just downstream from Bowdish Reservoir. The maximum storage capacity of Clarkville Pond is 165 acre feet and its drainage area is approximately 4.0 square miles. The dam was probably built in the mid 1700's and was raised 6 feet in 1872. It was used for generating mechanical power in the mill located immediately downstream of the dam. During the early 1900's there were some improvements made on the spillway and on the power canal. Presently it has only limited recreational and aesthetic purposes.

As a result of the visual inspection, hydrologic and hydraulic computations, and the review of limited available data regarding this facility, the dam is considered to be in POOR condition. To assure the long term performance of

this structure, several items of concern require further attention. The downstream walls have collapsed at numerous locations and the earth embankment is sloughing, particularly behind the collapsed sections. There is extensive tree and vegetative growth along the entire dam, and riprap is missing at numerous sections on the upstream slope. The spillway training walls are in an advanced state of deterioration; they have been undermined and are leaning towards the channel. The power canal is also in an advanced state of deterioration, and there is extensive seepage emerging along the entire length of the downstream toe of the dam.

The dam is classified as SMALL in size and as a HIGH hazard potential structure, in accordance with the recommended guidelines established by the Corps of Engineers.

The test flood for this dam (2,000 cfs) is one-half the Probable Maximum Flood ( $\frac{1}{2}$  PMF). This flood has an outflow discharge equal to 2,000 cfs and will overtop the dam by 1.1 feet. The maximum top of dam outflow capacity of the spillway and headrace crest is 600 cfs, which represents approximately 30% of the test flood.



It is recommended that the owner engage the services of a registered professional engineer to alleviate the problems listed under Sections 7.2 and 7.3 and perform a detailed hydrologic-hydraulic investigation to assess further the potential of overtopping the dam and the need for and the means to increase project discharge capacity. The above recommendations should be instituted IMMEDIATELY after receipt of this report.

LENARD & DILAJ ENGINEERING, INC.


By:

John F. Lenard  
John F. Lenard, P.E.,  
President


Michael Dilaj  
Michael Dilaj, P.E., Vice President  
Project Manager



This Phase I Inspection Report on Clarkville Pond Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgement and practice, and is hereby submitted for approval.



CARNEY M. TERZIAN, MEMBER  
Design Branch  
Engineering Division




JOSEPH W. FINEGAN, JR., MEMBER  
Water Control Branch  
Engineering Division



ARAMAST MAHTESIAN, CHAIRMAN  
Geotechnical Engineering Branch  
Engineering Division

APPROVAL RECOMMENDED:



JOE B. FRYAR  
Chief, Engineering Division

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigations, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation. However, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions will be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

## TABLE OF CONTENTS

	<u>Page</u>
LETTER OF TRANSMITTAL	
BRIEF ASSESSMENT	
REVIEW BOARD PAGE	
PREFACE	i
TABLE OF CONTENTS	ii
OVERVIEW PHOTO	v
LOCATION MAP	vi

## REPORT

### SECTION 1 - PROJECT INFORMATION

1.1 General	1
a. Authority	
b. Purpose of Inspection Program	
c. Scope of Inspection Program	
1.2 Description of Project	2
a. Location	
b. Description of Dam and Appurtenances	
c. Size Classification	
d. Hazard Classification	
e. Ownership	
f. Operator	
g. Purpose of Dam	
h. Design and Construction History	
i. Normal Operational Procedure	
1.3 Pertinent Data	4
a. Drainage	
b. Discharge at Dam Site	
c. Elevations	
d. Reservoir Length	
e. Storage	
f. Reservoir Surface Area	
g. Dam	
h. Diversion and Regulating Tunnel	
i. Spillway	
j. Regulating Outlet	

	<u>Page</u>
SECTION 2 - ENGINEERING DATA	
2.1 Design	8
2.2 Construction	8
2.3 Operation	8
2.4 Evaluation	8
a. Availability	
b. Adequacy	
c. Validity	
SECTION 3 - VISUAL INSPECTION	
3.1 Findings	9
a. General	
b. Dam	
c. Appurtenant Structures	
d. Reservoir Area	
e. Downstream Channel	
3.2 Evaluation	11
SECTION 4 - OPERATIONAL AND MAINTENANCE PROCEDURES	
4.1 Operational Procedures	13
a. General	
b. Description of any Warning System in Effect	
4.2 Maintenance Procedures	13
a. General	
b. Operating Facilities	
4.3 Evaluation	13
SECTION 5 - EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES	
5.1 General	14
5.2 Design Data	14
5.3 Experience Data	14

	<u>Page</u>
5.4 Test Flood Analysis	14
5.5 Dam Failure Analysis	15
SECTION 6 - EVALUATION OF STRUCTURAL STABILITY	
6.1 Visual Observation	16
6.2 Design and Construction Data	16
6.3 Post Construction Changes	16
6.4 Seismic Stability	16
SECTION 7 - ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	
7.1 Dam Assessment	17
a. Condition	
b. Adequacy of Information	
c. Urgency	
7.2 Recommendations	18
7.3 Remedial Measures	19
a. Operating and Maintenance Procedures	
7.4 Alternatives	19

#### APPENDICES

APPENDIX A - INSPECTION CHECKLIST

APPENDIX B - ENGINEERING DATA

APPENDIX C - PHOTOGRAPHS

APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS

APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL  
INVENTORY OF DAMS



OVERVIEW PHOTO

US ARMY ENGINEER DIV. NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS

LENARD DILAJ ENGINEERING, INC.  
STORRS, CONNECTICUT  
ENGINEER

NATIONAL PROGRAM OF  
INSPECTION OF  
NON-FED. DAMS

CLARKVILLE POND DAM  
GLOCESTER, RHODE ISLAND  
RI 01309  
JAN. 1981





## PHASE I INSPECTION REPORT

### SECTION I - PROJECT INFORMATION

#### 1.1 General:

- a. Authority: Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Lenard & Dilaj Engineering, Inc. has been retained by the New England Division to inspect and report on selected dams in the States of Connecticut and Rhode Island. Authorization and notice to proceed were issued to Lenard & Dilaj Engineering, Inc. under a letter of 6 November, 1980 from William E. Hodgson, Jr., Colonel, Corps of Engineers. Contract No. DACW33-81-C-0014 has been assigned by the Corps of Engineers for this work.
- b. Purpose of Inspection Program: The purposes of the program are to:
  1. Perform technical inspection and evaluation of non-federal dams to identify conditions requiring correction in a timely manner by non-federal interest.
  2. Encourage and prepare the states to quickly initiate effective dam inspection programs for non-federal dams.
  3. To update, verify and complete the National Inventory of Dams.
- c. Scope of Inspection Program: The scope of this Phase I inspection report includes:
  1. Gathering, reviewing and presenting all available data as can be obtained from the owners, previous owners, the state and other associated parties.
  2. A field inspection of the facility detailing the visual condition of the dam, embankments and appurtenant structures.

3. Computations concerning the hydraulics and hydrology of the facility and its relationship to the calculated flood through the existing spillway.
4. An assessment of the condition of the facility and corrective measures required.

It should be noted that this report does not pass judgment on the safety or stability of the dam other than on a visual basis. The inspection is to identify those features of the dam which need corrective action and/or further study.

## 1.2 Description of the Project:

- a. Location: The project is located on Mary Brown Brook, a tributary to the Five Mile River, which is located approximately 3 miles downstream of Clarkville Pond Dam. Mary Brown Brook and the Five Mile River are a part of the Quinebaug River Basin. The pond and dam are located in the Town of Glocester, County of Providence, and State of Rhode Island. The dam is located just 200 feet east of Pulaski Road, and is shown on the Thompson, Conn.-R.I. USGS quadrangle map, having coordinates  $41^{\circ} 55' 18''$  (north latitude) and  $71^{\circ} 47' 24''$  (west longitude).
- b. Description of Dam and Appurtenances: Clarkville Pond Dam is an earth embankment, approximately 400 feet long, with 2 dry masonry stone walls on the downstream side. It has an average height of 12 feet and a crest width of approximately 12 feet. Because of the advanced state of deterioration of the walls and due to the sloughing and erosion of the upstream and downstream slopes, no definite dimensions can be given.

The stone slab spillway is located near the left abutment of the dam. It is 28 feet wide and has two 4 foot high reinforced concrete training walls, which are in an advanced state of deterioration. The stone slabs in the spillway discharge channel are laid in a step-like manner from the crest to the streambed. Rods have been provided on the crest for the insertion of flashboards. At the right abutment of the dam is a power intake canal. This intake is located in line with the dam and consists of a reinforced concrete structure with a 24 inch diameter pipe. The gate on the intake pipe is missing. The power canal leads into a penstock and then into the mill which is located approximately 200 feet downstream of the dam.

Power generation or any other water use has been discontinued for some time. Presently the reservoir serves only to have an aesthetic value and has limited recreational use.

- c. Size Classification: With the pool level at the top of the dam, the dam's impoundment capacity is 165 acre feet and its maximum height is 14 feet. The dam is therefore classified as a SMALL structure in accordance with the recommended guidelines of the Corps of Engineers. Limits for such classifications are shown on page 1 of Appendix D.
- d. Hazard Classification: The dam is classified as having a HIGH hazard potential because there is a mill structure located immediately downstream of the dam and a residential unit which was recently constructed within the flood plain below the dam. Flooding of these structures may cause loss of more than a few lives and extensive property damage, particularly since the mill is being converted to residential use. The estimated prefailure depth at the location of the mill building and the residential unit adjacent to the mill building is 2 feet. Estimated water depth for a possible dam failure discharge of 12,000 cfs is 8 feet at this same location.
- e. Ownership: The Clarkville Pond Dam is owned by John Abbott of 192 Summit Street, Pawtucket, Rhode Island.
- f. Operator: There are no operating personnel other than the dam owner, John Abbott, 192 Summit Street, Pawtucket, Rhode Island, telephone (401) 568-8287.
- g. Purpose of Dam: The dam at Clarkville Pond presently has no other purpose than aesthetic value and limited recreational use.
- h. Design and Construction History: The dam was originally constructed in the mid 1700's and raised 6 feet in 1872. In 1910 there were improvements made to the power canal, and the present intake structure for the power canal was probably constructed at that time. (See more details of history in Appendix.)
- i. Normal Operating Procedures: There are no operating procedures at this dam. The power canal is presently closed off from the downstream end of the intake structure with a plywood sheet tied down with ropes.

### 1.3 Pertinent Data:

- a. Drainage Area: Clarkville Pond and its drainage area are located in Providence County in the north-westerly portion of Rhode Island. The basin is generally irregular in shape with a longitudinal northeast-southwest axis of approximately 3 miles and a width of 2 miles. The total drainage area for this study has been divided into two parts, one for Bowdish Reservoir of 3.1 square miles and one for Clarkville Pond of 0.9 square miles (See Watershed Map). Because of the large amount of storage available in Bowdish Reservoir, its influence on the inflow hydrograph to Clarkville Pond, both in terms of flow and time of concentration, was considerable. Because of the limited storage areas and watersheds, two other ponds were not considered in the calculation of the inflow hydrograph. These ponds were Wilbur Pond and Lake Washington, located in the northeasterly portion and southeasterly portion of the watershed, respectively. In total, the watershed area contributing to the inflow at Clarkville Pond is 4.0 square miles.

The topography of the basin consists of generally rolling terrain, with a substantial portion taken up by wetland areas and water bodies. Elevations range from a low of 564 feet at the spillway crest of Clarkville Pond Dam to a high of 760 in the southeasterly corner of the basin. Slopes are moderate with grades ranging generally from 5% to 15%.

- b. Discharge at Dam Site: No discharge records are maintained at this facility. There were no flashboards in place on the spillway crest at the time of this inspection, but the power canal was found to be closed off and inoperational. There is some limited discharge capability available over the crest of the power canal intake. Because this portion is ungated, its discharge has been included under the ungated spillway capacity. A more accurate breakdown may be found under the hydraulic calculations in Appendix D of this report.

- |  |  |
|--|--|
| 1. Outlet works:   | Inoperational<br>(Power canal discharges<br>into building) |
| 2. Maximum known flood at dam site:                      | Discharge unknown  |
| 3. Ungated spillway capacity at<br>top of dam:           | 611 cfs at Elev. 542.0                                     |
| 4. Ungated spillway capacity at<br>test flood elevation: | 896 cfs at Elev. 543.1                                     |

5. Gated spillway capacity at normal pool elevation: N/A
  6. Gated spillway capacity at test flood elevation: N/A
  7. Total spillway capacity at test flood elevation: 900 cfs at Elev. 543.1
  8. Total project discharge at top of dam: 600 cfs at Elev. 542.0
  9. Total project discharge at test flood elevation: 2,000 cfs at Elev. 543.1
- c. Elevation (Feet above National Geodetic Vertical Datum):
1. Streambed at toe of dam: 528.0
  2. Bottom of cutoff: Unknown
  3. Maximum tailwater: Unknown
  4. Normal pool: 538.0
  5. Full flood control pool: N/A
  6. Spillway crest: 538.0
  7. Design surcharge (original design): N/A
  8. Top of dam: 540.5 (varies)
  9. Test flood surcharge: 543.1
- d. Reservoir (Length in Feet):
1. Normal pool: 1,300
  2. Flood control pool: N/A
  3. Spillway crest pool: 1,300
  4. Top of dam: 1,600
  5. Test flood pool: 1,650
- e. Storage (acre-feet):
1. Normal pool: 93
  2. Flood control pool: N/A
  3. Spillway crest pool: 93

- |    |                  |     |
|----|------------------|-----|
| 4. | Top of dam:      | 165 |
| 5. | Test flood pool: | 193 |
- f. Reservoir Surface (acres):
- |    |                     |      |
|----|---------------------|------|
| 1. | Normal pool:        | 13   |
| 2. | Flood control pool: | N/A  |
| 3. | Spillway crest:     | 13   |
| 4. | Test flood pool:    | 27   |
| 5. | Top of dam:         | 23.5 |
- g. Dam:
- |    |                  |   |
|----|------------------|---|
| 1. | Type:            | Earth embankment  |
| 2. | Length:          | 400 feet  |
| 3. | Height:          | 14 feet   |
| 4. | Top width:       | 12 feet   |
| 5. | Side slopes:     | Upstream: 2H:1V<br>Downstream:<br>Vertical Stone Walls<br>w/1H:1V earth slope |
| 6. | Zoning:          | Unknown   |
| 7. | Impervious core: | Unknown   |
| 8. | Cutoff:          | Unknown   |
| 9. | Grout curtain:   | Unknown   |
- h. Diversion and Regulating Tunnel:N/A
- i. Spillway:
- |    |   |                                       |
|----|---|---------------------------------------|
| 1. | Type:                                     | Broad crest, stone<br>masonry surface |
| 2. | Length of weir:                           | 27.5 feet                             |
| 3. | Crest elevation (without<br>flashboards): | 538.0                                 |

- |                               |  |
|-------------------------------|--|
| 4. Gates:                     | None   |
| 5. U/S channel:               | Natural bed  |
| 6. D/S channel:               | Natural bed  |
| j. <u>Regulating Outlets:</u> | 24-inch inlet into power canal. Since the removal of the generating equipment, the flow would flood the mill structure. Canal not operational. |



SECTION 2  
ENGINEERING DATA

- 2.1 Design: No data on the design of the dam or appurtenances has been found and probably none exist.
- 2.2 Construction: The original dam at Clarkville Pond was probably build in the mid 1700's. In 1872 the dam was raised 6 feet. At this time it was used for power generation. The power canal was reconstructed after 1910. The reinforced concrete construction of the intake structure and spillway walls probably dates from that period.
- 2.3 Operation: This dam appears to have been constructed for power generating purposes. The equipment has been disassembled and presently the pond serves only recreational and aesthetic purposes. Indications are that flashboards were used at the spillway in the past. Presently, only the iron bars originally used to hold the boards are in place at the crest of the spillway. There are no records kept at the facilities.
- 2.4 Evaluation:
- a. Availability: There are no computations, drawings, or operational procedures available for this dam.
  - b. Adequacy: Since there is no design or construction information available, the information presented in this report is based principally on the visual observations of the inspection team.
  - c. Validity: Due to the lack of available data, the conclusions and recommendations found in this report are based on the visual inspection and hydrologic/hydraulic computations.

### SECTION 3

#### VISUAL INSPECTION

##### 3.1 Findings:

- a. General: An inspection of Clarkville Pond Dam was performed on 14 November 1980 by Lenard & Dilaj Engineering, Inc., with the assistance of Geotechnical Engineers, Inc. The temperature on this day was in the 30°- 40°F range, with clear and sunny skies. The ground was clear of snow.

As a result of the visual inspection, the dam at Clarkville Pond and its appurtenances are judged to be in POOR condition. The dam is an earth embankment with downstream walls consisting of a 2 to 3 foot high dry masonry knee wall and an 8 foot high dry masonry wall. Considerable portions of these walls are collapsed or are bulging extensively. The earth embankment behind the walls is sloughing, and there is very extensive seepage all along the downstream toe of the dam.

The spillway training walls are in a state of advanced deterioration, being undermined at the base and leaning outward. The dike forming the left bank of the power canal, as well as the concrete walls at the downstream end of the canal are also in a state of advanced deterioration.

At the time of inspection, the water level in the reservoir was at spillway crest elevation of 542 feet.

- b. Dam: The dam is an earth embankment with downstream dry masonry stone walls. There is a 2 to 3 foot high knee wall and approximately 15 feet towards the reservoir, there is an approximately 8 to 10 foot high dry masonry stone wall. There are no construction or design drawings available. Records indicate that the dam was constructed in the 1700's and was raised in 1872. They also indicate that the location of the dam has not been changed and a 1910 plan shows the impoundment to be practically identical in area to today's pond.
1. Crest: The crest of the dam is very uneven in width and elevation and is covered with trees and grass. There is a foot path along the approximate

centerline of the crest (Photo 2). At its lowest point the crest is 0.6 feet lower than near the spillway. The 1 to 2 foot settlements of the crest are probably due to the collapse of the downstream stone masonry walls.

2. Upstream slope: The upstream slope (2H:1V) is partially covered with riprap (Photo 1). This cover is very uneven and the size of the riprap ranges from 6 inches to 30 inches in size. There is extensive brush and tree growth between the riprap.
3. Downstream slope: The state of advanced deterioration of the downstream slope (1H:1V) is due to the collapse of the stone walls, sloughing and erosion. Approximately within 30 feet to the right of the spillway, the wall is completely collapsed and there is extensive sloughing on the earth embankment (Photo 5). There is also a 20 inch diameter tree growing on the downstream slope in this area. Approximately 70 feet from the spillway, another section of the wall has crumbled, due probably in part to the additional pressure of a tree growing at this location. There are large voids in the wall and the earth embankment is sloughing. Another section of the wall, approximately 50 feet left of the power canal, has bulged extensively (Photo 9 and 10).

The knee stone wall is in a state of deterioration along most of the dam. Long sections of it have completely collapsed and the slope behind it has sloughed. There is extensive tree growth also behind the knee wall. There is extensive seepage along the entire length of the toe of the dam with a typical rust-brown colored water with a surficial oil sheen (Photo 8). Because of marsh type vegetation and ponding of the water downstream of the dam, flow from seepage is not apparent. However, the seepage flow becomes noticeable at the culvert on Pulaski Road. Looking upstream from this culvert (Photo 14) one can see two converging streams. One stream on the right is coming from the spillway while the stream from the left is carrying almost as much discharge from the leakage.

- c. Appurtenant structures: The appurtenant structures for this dam are the overflow spillway, and the power canal at the intake structure.
1. Overflow spillway: The overflow spillway consists of a dry stone masonry wall built with large stone

slabs stepped down in numerous stages; it is in good condition. The training walls are of reinforced concrete placed against dry masonry walls and are in poor condition. The left training wall has been undermined and has cracked and tilted. (Photo 12). Tilting may have occurred partly as the result of pressures due to a 36 inch tree growing immediately behind this training wall. The right training wall is also undermined and cracked at numerous locations (Photo 4). The downstream part of the right training wall is of stone masonry and has partially collapsed (Photo 5). There are numerous trees growing behind the right and left training walls. Five steel bars at the spillway crest support flashboards for raising the pond elevation. These bars may cause obstruction by blocking the path of floating debris.

2. Power canal: The intake structure for the power canal is a reinforced concrete structure (Photo 7) with a 24 inch pipe. The gate is missing and flow is blocked by plywood attached with ropes on the downstream face. The concrete is cracked at numerous locations.

The walls of the power canal near the penstock have bulged and crumbled, and are in a state of advanced deterioration. The left earth dike of the power canal has also deteriorated, is sloughing, and has partially collapsed.

- d. Reservoir Area: There is considerable siltation at the spillway area in the reservoir. There are only a few houses along the shores of the reservoir. The reservoir is used for intermittent recreation by the neighboring residents.
- e. Downstream Channel: The spillway of the Clarkville Pond Dam discharges into Mary Brown Brook. Approximately 300 feet downstream from the spillway the brook passes under Pulaski Road in a culvert. A considerable amount of flow enters this brook just upstream from the culvert. This additional flow emanates from seepage.

3.2 Evaluation: Based on the visual inspection, the overall condition of the dam and its appurtenances is poor.

- a. Extensive tree and brush growth is on the crest of the dam, on the upstream and downstream slopes, behind the spillway training walls, and at the power canal intake.

- b. The stone masonry walls have collapsed at numerous locations and the earth embankment is sloughing.
- c. The spillway training walls have been undermined, have severe cracks and are leaning.
- d. Riprap is missing in many areas of the upstream slope.
- e. There is very extensive seepage exiting at the downstream toe along the entire length of the dam.
- f. The power canal, its intake structure, and the training walls are in an advanced state of deterioration.

## SECTION 4

### OPERATIONAL AND MAINTENANCE PROCEDURES

#### 4.1 Operational Procedures:

- a. General: The owner does not reside at the dam and there is no one present at the site to attend to any routine or emergency functions. There are no formal operational procedures in effect at the dam.
- b. Description of any Warning System in Effect: There are no warning systems in effect at this facility.

#### 4.2 Maintenance Procedures:

- a. General: There is no maintenance at this dam as evidenced, in particular, by the growth of trees and vegetation on the embankments. Indications are that the dam and appurtenant facilities have not been maintained for at least the past decade.
- b. Operating Facilities: Discharge into the power canal is blocked by a plywood board placed over the downstream side of the inlet (Photo 7). The power generating equipment is removed and, if flow would be discharged into the canal, it would spill into the mill building. The spillway training walls are crumbling and steel bars at the crest of the spillway may constrict the free passage of flow. The blockage of the power canal intake was the only evidence of activity at the facility.

#### 4.3 Evaluation: There is no indication that the dam, spillway and appurtenant facilities are being maintained. An emergency warning system should be developed as discussed in Section 7.3 of this report.

## SECTION 5

### EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES

- 5.1 General: Clarkville Pond Dam is an earth embankment dam with two vertical downstream stone masonry walls. The dam is about 400 feet long, 12 feet wide at the crest, and 14 feet high at the streambed. There is a stone masonry spillway 27.5 feet wide and 4 feet high which, for purposes of hydraulic calculations, was considered as a broad crested weir. Because the power generation equipment at the mill is now inoperable, the head race was not considered as an integral part of the discharge capacity of the dam. Its only contribution is to provide some additional spillway capacity at the intake structure, where the top portion would act as a weir to allow flow over the dam.

The downstream channel is approximately 15 feet wide at the base of the dam and continues at this width to the road crossing 200 feet downstream. The channel winds in this area between the dam and the road, and its banks are generally overgrown with trees and brush.

The watershed covers an area of 4.0 square miles, of which 3.1 square miles contributes to Bowdish Reservoir, which lies just upstream from Clarkville Pond. Because of the storage capacity available at Bowdish Reservoir, its effect on the flows at Clarkville Pond Dam is significant. For this reason, the flood was routed through both Bowdish Reservoir and Clarkville Pond.

At spillway elevation, Clarkville Pond has a storage capacity of 93 acre feet. This increases to 165 acre feet at the top of the dam.

- 5.2 Design Data: No design data was available for Clarkville Pond Dam.
- 5.3 Experience Data: No records on past experience were found to be available for this site.
- 5.4 Test Flood Analysis: Based on the "Recommended Guidelines for Safety Inspection of Dams", Clarkville Pond Dam is

classified as SMALL in size with a HIGH hazard potential. The test flood for these conditions ranges from half the Probable Maximum Flood to the Probable Maximum Flood ( $\frac{1}{2}$  PMF to PMF). Because of the potential downstream damage involved with failure and based on the size and storage capacity of the dam, the  $\frac{1}{2}$  PMF was chosen as the test flood.

Using the HEC-1 Flood Hydrograph Computer Program developed by the Army Corps of Engineers for dam safety investigations, the inflow and outflow for the test flood were both found to be 2,000 cfs (500 CSM). As a basis of comparison, the PMF resulted in an inflow of 6,350 cfs and an outflow of 6,300 cfs. The outflow capacity of Clarkville Pond Dam at the top of the dam is 600 cfs, which represents 30% of the test flood outflow.

As previously mentioned, the storage in Bowdish Reservoir has a significant effect on the inflow hydrograph to Clarkville Pond. This storage was included in the analysis, as shown by the calculations in Appendix D of this report.

- 5.5 Dam Failure Analysis: A dam failure analysis was performed using the "Rule of Thumb" method for estimating downstream dam failure hydrographs, as developed by the Corps of Engineers. Failure was assumed to occur when the water level in the pond was at the level of the top of the dam. The spillway discharge just prior to the dam's failure would be 611 cfs, producing a depth of flow of approximately 2 feet in the vicinity of the mill and residence just downstream of the dam (See Overview Photo). The calculated dam failure discharge is 12,000 cfs, which will produce a depth of flow of approximately 8 feet at the same location. This means an increase of 6 feet in the water depth at the time of failure. The analysis covered a distance of 3,800 feet downstream, as shown by the calculations in Appendix D. The depth of flow at that point was calculated to be 4.1 feet for the dam failure.

A 40% breach measured at the mid height of the dam could cause significant downstream damage and result in the loss of more than a few lives; therefore, the dam is classified as having a HIGH hazard potential. The mill complex, now being converted for residential use and the residence just downstream of the dam would receive the greatest damage. Appreciable damage could also occur at the town road (Pulaski Road) and Route 44, about 3,000 feet downstream.



## SECTION 6

### EVALUATION OF STRUCTURAL STABILITY

- 6.1 Visual Observations: The visual inspection of the dam and appurtenant structures revealed a condition of deteriorating stability as indicated by the following:
- a. The stone masonry walls have collapsed at numerous locations and the earth embankment is sloughing.
  - b. The spillway training walls have been undermined, have severe cracks and are leaning.
  - c. There is very extensive seepage exiting at the downstream toe along the entire length of the dam.
  - d. The power canal, its intake structure, and the training walls are in an advanced state of deterioration.
- 6.2 Design and Construction Data: There is no design and construction data available to permit a formal evaluation of the stability of the dam. The evaluation of stability is based on visual inspection. According to information obtained from residents of the area, the dam has not been overtopped over the past few decades. There are no operating records available at this location.
- 6.3 Post Construction Changes: The reinforced concrete structures indicate that there have been modifications since the construction of the dam. As discussed in other parts of this report, these changes took place approximately 70 years ago.
- 6.4 Seismic Stability: Clarkville Pond Dam is located in Seismic Zone 1 and, according to the Corps of Engineers recommended guidelines, does not require evaluation for seismic stability.

## SECTION 7

### ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

#### 7.1 Dam Assessment:

- a. Condition: The visual inspection indicated that the Clarkville Pond Dam is in poor condition. The major concerns regarding the future performance of this dam include:
1. Extensive tree and bush growth at every location on the dam, near the spillway training walls and the power canal intake structure.
  2. The downstream stone walls have collapsed at numerous locations.
  3. The earth embankment is sloughing at numerous locations, particularly behind collapsed sections of the downstream walls.
  4. Riprap is missing at several locations on the upstream slope of the dam.
  5. The spillway training walls are in an advanced state of deterioration; they are undermined and leaning towards the channel.
  6. Vertical steel bars used to support flashboards in the spillway may obstruct the flow during flood periods. These bars should be removed.
  7. The power canal intake structure and the canal itself are in an advanced state of deterioration. The gate is missing at the intake structure.
  8. There is extensive seepage emerging at the downstream toe along the entire length of the dam.
  9. Based on hydraulic calculations, the spillway capacity at the top of the dam is 600 cfs, representing only about 30% of the test flood flow of 2,000 cfs.
- b. Adequacy of Information: The lack of in-depth engineering data did not allow for a definitive review.

Therefore, the adequacy of this dam could not be assessed from the standpoint of reviewing design and construction data; it is based primarily on visual inspection and sound engineering judgment.

- c. Urgency: The recommendations and remedial measures described below should be implemented by the owner IMMEDIATELY after receipt of this Phase I inspection report.

7.2 Recommendations: The owner should engage the services of a professional registered engineer experienced in the design of earth dams to accomplish the following:

- a. Perform a detailed hydrologic-hydraulic investigation to assess further the potential of overtopping the dam and the need for and the means to increase project discharge capacity.
- b. Assess the need for and means to provide a low level regulating outlet that would allow drawdown of the pool.
- c. Engineering plans are required for the reconstruction of the downstream section of the dam. Plans should include all construction details for the proper restoration of the stone wall and the earth embankment behind the stone wall or, alternatively, for construction of a downstream section of compacted earth. Installation of filter or drainage layers may be necessary for both alternative repairs. The crest elevation of the dam should be restored to an even grade.
- d. Trees and brush growing on the entire dam and appurtenant structures should be cut. The stumps and root systems of trees should be removed and holes should be backfilled with an appropriately compacted soil. In addition, a 30 foot peripheral area downstream of the toe of the dam should be cleared.
- e. Investigate seepage along the toe of the dam and consider the installation of toe drains along the entire downstream toe of the dam. Discharge from these toe drains should be monitored and recorded.
- f. The spillway training walls should be reconstructed. The deteriorated concrete walls must be removed and new walls should be erected according to plans prepared by an engineer.
- g. The power canal intake structure should be reconstructed or removed and properly filled.
- h. The riprap protection along the upstream face of the dam embankment should be re-established.

- i. A topographic survey of the dam and its appurtenances should be made that will result in drawings of the existing facility to be used as a basis for the construction plans.

### 7.3 Remedial Measures:

#### a. Operating and Maintenance Procedures:

1. After removal of trees and brush in accordance with 7.2d, grass should be planted and periodically cut in these disturbed areas to protect the embankment from erosion.
2. Emergency procedures consisting of an operations plan and warning system for downstream residences should be developed and implemented. During intense rainfall the dam should be continuously monitored.
3. Technical inspection of this facility should be made on an annual basis by a qualified registered professional engineer.
4. Develop a system for recording of data such as water levels, discharges, and drawdown, to assist those responsible for monitoring the operation of the structure.
5. Remove steel flashboard support bars from spillway.
6. Remove the plywood stop from the intake pipe and replace it with an operational gate.

- ### 7.4 Alternatives:
- As an alternative to the above recommendations and remedial measures, the Owner should consider removing the dam.

## **APPENDIX A**

### **INSPECTION CHECKLIST**

# VISUAL INSPECTION CHECKLIST PARTY ORGANIZATION

PROJECT CLARKVILLE POND DAM

DATE November 14, 1980

TIME 1:00 P.M.

WEATHER Cloudy, balmy

W.S. ELEV. At Spillway U.S.        DN.S.       

## PARTY:

- |                                      |   |
|--------------------------------------|---|
| 1. <u>Gonzalo Castro, G.E.I.</u>     | 6. <u>Kent Healy, L.D.F.I.</u>                |
| 2. <u>John Lenard, L.D.E.I.</u>      | 7. <u>                                  </u>  |
| 3. <u>Michael Dilaj, L.D.E.I.</u>    | 8. <u>                                  </u>  |
| 4. <u>Eric Ohlund, L.D.E.I.</u>      | 9. <u>                                  </u>  |
| 5. <u>Gregory Blessing, L.D.E.I.</u> | 10. <u>                                  </u> |

PROJECT FEATURE	INSPECTED BY	REMARKS
1. <u>Hydraulics</u>	<u>Michael Dilaj</u>	
2. <u>Structural</u>	<u>John Lenard</u>	
3. <u>Geotechnical</u>	<u>Gonzalo Castro</u>	
4. <u>Geotechnical</u>	<u>Kent Healy</u>	
5. <u>Survey</u>	<u>Eric Ohlund</u>	
6. <u>Survey</u>	<u>Gregory Blessing</u>	
7. <u>                  </u>		
8. <u>                  </u>		
9. <u>                  </u>		
10. <u>                  </u>		

# PERIODIC INSPECTION CHECKLIST

PROJECT CLARKVILLE POND DAM DATE November 14, 1980  
 PROJECT FEATURE \_\_\_\_\_ NAME \_\_\_\_\_  
 DISCIPLINE \_\_\_\_\_ NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation	
Current Pool Elevation	
Maximum Impoundment to Date	
Surface Cracks	<i>None observed</i>
Pavement Condition	<i>Not applicable</i>
Movement or Settlement of Crest	<i>Severe sloughing of downstream part of crest.</i>
Lateral Movement	<i>Collapsed downstream wall</i>
Vertical Alignment	<i>Crest is irregular.</i>
Horizontal Alignment	<i>Too irregular to judge</i>
Condition at Abutment	<i>Fair</i>
Indications of Movement of Structural Items on Slopes	<i>Not applicable</i>
Trespassing on Slopes	<i>Foot paths on slopes and crest</i>
Sloughing or Erosion of Slopes	<i>Severe sloughing downstream slope due to wall collapse</i>
Rock Slope Protection - Riprap Failures	<i>No slope protection, scattered boulders</i>
Unusual Movement or Cracking at or Near Toe	<i>Knee wall in a state of collapse</i>
Embankment or Downstream Seepage	<i>Extensive seepage downstream of dam starting at toe</i>
Piping or Boils	<i>None observed</i>
Foundation Drainage Features	<i>None known</i>
Toe Drains	<i>None known</i>
Instrumentation System	<i>None known</i>
Vegetation	<i>Heavy tree and brush cover. Tree sizes up to 30" in diameter.</i>

# PERIODIC INSPECTION CHECKLIST

PROJECT CLARKVILLE POND DAM DATE November 14, 1980  
 PROJECT FEATURE \_\_\_\_\_ NAME \_\_\_\_\_  
 DISCIPLINE \_\_\_\_\_ NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>DIKE EMBANKMENT (POWER CANAL DIKE)</u>	
Crest Elevation	
Current Pool Elevation	
Maximum Impoundment to Date	
Surface Cracks	<i>None observed</i>
Pavement Condition	<i>Not applicable</i>
Movement or Settlement of Crest	<i>Sloughing because of stone wall failure</i>
Lateral Movement	<i>Collapsed</i>
Vertical Alignment	<i>Too irregular to judge</i>
Horizontal Alignment	<i>Too irregular to judge</i>
Condition at Abutment and at Concrete Structures	<i>Fair</i>
Indications of Movement of Structural Items on Slopes	<i>Not applicable</i>
Trespassing on Slopes	<i>Several footpaths</i>
Sloughing or Erosion of Slopes or Abutments	<i>Severe sloughing of slopes</i>
Rock Slope Protection - Riprap Failures	<i>Not applicable</i>
Unusual Movement or Cracking at or Near Toes	<i>None observed</i>
Unusual Embankment or Downstream Seepage	<i>Not applicable</i>
Piping or Boils	<i>Not applicable</i>
Foundation Drainage Features	<i>Not applicable</i>
Toe Drains	<i>Not applicable</i>
Instrumentation System	<i>Not applicable</i>
Vegetation	<i>Heavy tree and brush cover</i>



## PERIODIC INSPECTION CHECKLIST

PROJECT CLARKVILLE POND DAM

DATE November 14, 1980

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME. \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u>	
a. Approach Channel	<i>No approach channel</i>
Slope Conditions	
Bottom Conditions	
Rock Slides or Falls	
Log Boom	
Debris	
Condition of Concrete Lining	
Drains or Weep Holes	
b. Intake Structure	<i>Poor, cracked, spalling</i>
Condition of Concrete	
Stop Logs and Slots	<i>None</i>
	<i>Makeshift gate on intake pipe, downstream end.</i>

# PERIODIC INSPECTION CHECKLIST

PROJECT CLARKVILLE POND DAM

DATE November 14, 1980

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - CONTROL TOWER</u></p> <p>a. Concrete and Structural</p> <p>General Condition</p> <p>Condition of Joints</p> <p>Spalling</p> <p>Visible Reinforcing</p> <p>Rusting or Staining of Concrete</p> <p>Any Seepage or Efflorescence</p> <p>Joint Alignment</p> <p>Unusual Seepage or Leaks in Gate Chamber</p> <p>Cracks</p> <p>Rusting or Corrosion of Steel</p> <p>b. Mechanical and Electrical</p> <p>Air Vents</p> <p>Float Wells</p> <p>Crane Hoist</p> <p>Elevator</p> <p>Hydraulic System</p> <p>Service Gates</p> <p>Emergency Gates</p> <p>Lightning Protection System</p> <p>Emergency Power System</p> <p>Wiring and Lighting System</p>	<p>None</p>

# PERIODIC INSPECTION CHECKLIST

PROJECT CLARKVILLE POND DAM

DATE November 14, 1980

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

## AREA EVALUATED

## CONDITION

### OUTLET WORKS - TRANSITION AND CONDUIT

General Condition of Concrete

Rust or Staining on Concrete

Spalling

Erosion or Cavitation

Cracking

Alignment of Monoliths

Alignment of Joints

Numbering of Monoliths

*There is no conduit at this facility.  
(See next page)*

# PERIODIC INSPECTION CHECKLIST

PROJECT CLARKVILLE FOND DAM DATE November 14, 1980  
 PROJECT FEATURE \_\_\_\_\_ NAME \_\_\_\_\_  
 DISCIPLINE \_\_\_\_\_ NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u>	<i>Power house inlet channel</i>
General Condition of Concrete	<i>Poor</i>
Rust or Staining	<i>Rusty</i>
Spalling	<i>Severe, numerous cracks</i>
Erosion or Cavitation	<i>Not applicable</i>
Visible Reinforcing	<i>Yes, near entrance to covered conduit</i>
Any Seepage or Efflorescence	<i>Not applicable</i>
Condition at Joints	<i>Not applicable</i>
Drain holes	<i>None in the concrete section</i>
Channel	<i>Poor condition, collapsed stone walls</i>
Loose Rock or Trees Overhanging Channel	<i>Many trees overhanging channel</i>
Condition of Discharge Channel	<i>Poor</i>

# PERIODIC INSPECTION CHECKLIST

PROJECT CLARKVILLE POND DAM DATE November 14, 1980  
 PROJECT FEATURE \_\_\_\_\_ NAME \_\_\_\_\_  
 DISCIPLINE \_\_\_\_\_ NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	
a. Approach Channel	<i>None</i>
General Condition	
Loose Rock Overhanging Channel	
Trees Overhanging Channel	
Floor of Approach Channel	
b. Weir and Training Walls	
General Condition of Concrete	<i>Poor, advanced state of undermining of training walls</i>
Rust or Staining	<i>None observed</i>
Spalling	<i>Yes, severe</i>
Any Visible Reinforcing	<i>No</i>
Any Seepage or Efflorescence	<i>Not observable, water going over spillway</i>
Drain Holes	<i>None observed</i>
c. Discharge Channel	
General Condition	<i>Fair</i>
Loose Rock Overhanging Channel	<i>None</i>
Trees Overhanging Channel	<i>Numerous</i>
Floor of Channel	<i>Irregular, boulders and stones rolled into channel</i>
Other Obstructions	<i>None</i>
Other Comments	<i>Reinforcing bars on spillway for stop logs represent potential obstruction to flow.</i>
A-2	

# PERIODIC INSPECTION CHECKLIST


PROJECT CLARKVILLE POND DAM DATE November 11, 1967  
 PROJECT FEATURE \_\_\_\_\_ NAME \_\_\_\_\_  
 DISCIPLINE \_\_\_\_\_ NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - SERVICE BRIDGE</u></p> <p>a. Super Structure</p> <ul style="list-style-type: none"> <li>Bearings</li> <li>Anchor Bolts</li> <li>Bridge Seat</li> <li>Longitudinal Members</li> <li>Underside of Deck</li> <li>Secondary Bracing</li> <li>Deck</li> <li>Drainage System</li> <li>Railings</li> <li>Expansion Joints</li> <li>Paint</li> </ul> <p>b. Abutment &amp; Piers</p> <ul style="list-style-type: none"> <li>General Condition of Concrete</li> <li>Alignment of Abutment</li> <li>Approach to Bridge</li> <li>Condition of Seat &amp; Backwall</li> </ul> <p style="text-align: right;">A-2</p>	<p><i>There is no service bridge at this facility.</i></p>

## **APPENDIX B**

ENGINEERING DATA

# CLARKVILLE POND



LEONARD DILAJ ENGINEERING, INC. STORRS CONNECTICUT ENGINEER		US ARMY ENGINEER DIV. NEW ENGLAND CORPS OF ENGINEERS WALTHAM MASSACHUSETTS	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
<b>SITE PLAN</b>			
<b>CLARKVILLE POND DAM</b> <b>GLOUCESTER, RHODE ISLAND</b>			
DESIGN BY	CHECKED BY	APPROVED BY	SCALE
			AS SHOWN
DATE: 10/25/57		SHEET	



### HISTORY OF CLARKVILLE POND DAM

The first dam at Clarkville Pond was probably built in the mid 1700's. The earliest reference to a Clarkville dam was that in "1818 a mill at Clarkville was built by the Arnold Brothers."<sup>1</sup> In the 1800's the Clarkville Pond was called Bowdish or Bowditch Mill Pond.


According to the Gloucester land records, on April 1, 1872 the dam was to be raised six feet.<sup>2</sup> The owners of the dam and mill at that time, F.R. White and Company, came to an agreement with four other downstream mill owners to share the expenses of raising and maintaining the dam. F.R. White and Company wanted to increase its draw of water to a maximum of 30 horsepower or 24 feet of head. The 30 horsepower draw of water was to be tried for 3 years provided the pond could replenish itself; keeping an adequate outflow for the downstream mills.

A 1910 map of the Bowditch Mill Pond (Clarkville Pond) delineates the pond boundaries, which are similar to those of today (see map). The raceway at the north end of the dam was probably constructed between 1910 and 1930.

A recent owner of the mill property, Erich Schmidt, recalls that the dam was not overtopped due to the hurricanes of 1938 or 1955. The 1938 storm flow was "easily" handled by the two spillways. The mill property and dam are presently owned by John Abbott.

<sup>1</sup>Richmond Kent, The History of Chepachet

<sup>2</sup>Gloucester Land Records, Volume 31, pages 34-35



THE BOWDITCH MILLS PROPERTY  
DEXTER ELLIOTT PROP.  
WEST GLOUCESTER, RHODE ISLAND


SURVEYED BY OSCAR MUNYAN  
MARCH 1910  
SCALE 10 RODS TO AN INCH  
POND LINE ASSUMED EXCEPT ON  
THE CARROLL ESTATE.

TRACED FROM MAP ON FILE AT  
THE GLOUCESTER TOWN HALL.

## **APPENDIX C**

### **PHOTOGRAPHS**

# CLARKVILLE POND



LEONARD DILLAS ENGINEERING, INC.	US ARMY ENGINEER DIV NEW ENGLAND
SPRING CORNER, CT	CORPS OF ENG APPLS
BRANFORD	WALLINGFORD, CT 06495
NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS	
<h2>PHOTO INDEX</h2> <h3>CLARKVILLE POND DAM</h3> <h3>GLOUCESTER, RHODE ISLAND</h3>	
DATE: 1/1/78	BY: J. L. DILLAS
APPROVED BY: J. L. DILLAS	DATE: 1/1/78



Photo 1. Overall view of dam from left abutment. Note spillway training wall at left, extensive tree growth on dam, and irregular rip-rap on upstream slope. Note faint outline of white mill structure in background.



Photo 2. View of dam crest from right abutment towards left abutment. Note sloughing on downstream slope at right of picture due to collapse of downstream stone wall, extensive tree growth on crest of dam, and footpath.

US ARMY ENGINEER DIV. NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS

LENARD DILAJ ENGINEERING, INC.  
STORRS, CONNECTICUT  
ENGINEER

NATIONAL PROGRAM OF  
INSPECTION OF  
NON-FED. DAMS

CLARKVILLE POND DAM  
GLOCESTER, RHODE ISLAND  
RI 01309  
JAN. 1981  
C-2



Photo 3. Downstream face of spillway. Note steel bars on crest for batter boards.



Photo 4. Right training wall of spillway. Note undermining in reinforced concrete wall and steel bars on crest of spillway.

US ARMY ENGINEER DIV. NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS

LENARD DILAJ ENGINEERING, INC.  
STORRS CONNECTICUT  
ENGINEER

NATIONAL PROGRAM OF  
INSPECTION OF  
NON-FED. DAMS

CLARKVILLE POND DAM  
GLOCESTER, RHODE ISLAND  
RI 01309  
JAN. 1981  
C-3



Photo 5. Right side of spillway looking towards dam embankment. Note sloughing and collapsed sections of downstream stone wall of dam.



Photo 6. Downstream stone wall near right abutment of dam. Note collapsed stone wall and tree growing behind wall.

US ARMY ENGINEER DIV. NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS

LENARD DILAJ ENGINEERING, INC.  
STORMS CONSULTANT  
ENGINEER

NATIONAL PROGRAM OF  
INSPECTION OF  
NON-FED. DAMS

CLARKVILLE POND DAM  
GLOUCESTER, RHODE ISLAND

RI 01309

JAN. 1981

C-4




Photo 7

Intake structure for power canal. Note makeshift "gate" installed on downstream side of intake pipe and cracked concrete.



Photo 8

Section of knee wall on downstream side of dam. Note seepage at toe of wall.

US ARMY ENGINEER DIV. NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS

LENAHO DILAJ ENGINEERING, INC.  
STORRS, CONNECTICUT  
ENGINEER

NATIONAL PROGRAM OF  
INSPECTION OF  
NON-FED. DAMS

CLARKVILLE POND DAM  
GLOCESTER, RHODE ISLAND  
RI 01309  
JAN. 1981  
C-5





Photo 9

Bulging section of downstream stone wall with tree growing on top of embankment.



Photo 10

Same stone wall viewed from downstream side. Note large openings between stones.

US ARMY ENGINEER DIV. NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS

LENARD DILAJ ENGINEERING, INC.  
STORRS CONNECTICUT  
ENGINEER

NATIONAL PROGRAM OF  
INSPECTION OF  
NON-FED. DAMS

CLAPKVILLE POND DAM  
GLOCESTER, RHODE ISLAND  
RT 01309  
JAN. 198  
C-6



Photo 11

Left training wall of spillway.  
Note cracked sections and under-  
mining of reinforced concrete  
portion of wall.



Photo 12

Close up view of Photo 11.  
Note the vertical outward  
tilting of the reinforced  
concrete training wall.

US ARMY ENGINEER DIV. NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS

LENARD DILAJ ENGINEERING, INC.  
STORRS, CONNECTICUT  
ENGINEER

NATIONAL PROGRAM OF  
INSPECTION OF  
NON-FED. DAMS

CLARKVILLE POND DAM  
GLOCESTER, RHODE ISLAND  
RI 01309  
JAN. 1981  
C-7



Photo 13. Downstream spillway channel.




Photo 14. Stream as observed from Pulaski Road crossing. Flow from the spillway is at the right of the photo, while a stream carrying seepage flow is at the left. Note the color of the seepage flow.

US ARMY ENGINEER DIV. NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS

LENARD DILAJ ENGINEERING, INC.  
STORRS CONNECTICUT  
ENGINEER

NATIONAL PROGRAM OF  
INSPECTION OF  
NON-FED. DAMS

CLARKVILLE POND DAM  
GLACESTER, RHODE ISLAND  
RI 01309  
JAN. 1981  
C-8

## **APPENDIX D**

### **HYDROLOGIC AND HYDRAULIC COMPUTATIONS**

# LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB Contract No. DACW33-81-C-0014

SHEET NO \_\_\_\_\_ OF \_\_\_\_\_

CALCULATED BY K. A. DATE 2/13/81

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_

SCALE None

CLARKVILLE POND DAM

## DETERMINATION OF SPILLWAY TEST FLOOD\*

### A. SIZE CLASSIFICATION

Based on either storage or height

THIS DAM:

Small Storage 50-999 Ac.-Ft.  
Height 25-39 Ft.

165 Ac. Ft.  
14 Ft.

Intermediate Storage 1,000-50,000 Ac.Ft.  
Height 40-100 Ft.

Large Storage More than 50,000 Ac.-Ft.  
Height Greater than 100 Ft.

### B. HAZARD POTENTIAL CLASSIFICATION

Category	Loss of Life	Economic Loss
Low	None expected	Minimal
Significant	Few	<u>Appreciable</u>
<u>High</u>	<u>More than few</u>	Excessive


Hazard Classification HIGH

### C. HYDROLOGIC EVALUATION GUIDELINES

Hazard	Size	Spillway Test Flood
Low	Small	50 to 100-Year Frequency
	Intermediate	100-Year Frequency to $\frac{1}{2}$ PMF
	Large	$\frac{1}{2}$ PMF to PMF
Significant	Small	100-Year Frequency to $\frac{1}{2}$ PMF
	Intermediate	$\frac{1}{2}$ PMF to PMF
	Large	PMF
<u>High</u>	<u>Small</u>	<u><math>\frac{1}{2}</math> PMF to PMF</u>
	Intermediate	PMF
	Large	PMF

Spillway Test Flood  $\frac{1}{2}$  PMF

\* Based upon "Recommended Guidelines for Safety Inspection of Dams" Department of the Army, Office of the Chief of Engineers, November 1976.



22 04700 02/05/01.  
Y1450 12.50.54.

JOB SPECIFICATION									
NO	NAME	MIN	DAY	TIME	WEEK	PLT	IPRT	NSIAN	
1	6	30	0	0	0	0	4	0	
			JOB	NOT	LEOPT	TRAC			
			5	0	0	0			

MULTI-PLANAL ANALYSES TO BE PERFORMED

$\text{SOL} =$	.19	.20	.30	.50	.70	1.00
$\text{PROB} =$	.10	.20	.30	.50	.70	1.00

# UNIT 1

# SI-M-A-FA RUNOFF COMPUTATION

CALCULATION OF DEFLECTION IN WALLS AND JOINTS

ISTAG	ICOMP	IECC	ITYPE	JPLT	JPRP	INAME	ISTAGE	IAINT
1	1	1	0	1	0	1	0	0

NY 2. (2) 2544 1, 47 A

	TABLE	SURF	TOTAL	RATIO	ISAE	LOCAL
1970	3.11	6.82	9.93	0.300	0	0
1971	3.11	6.82	9.93	0.300	0	0

2

25 200 444

100

MISS DATA

[illegible]

U.S. IT INVESTMENT DATA

$C_2 = 6.61$

RECEIVED  
JUL 1 - 1961  
61-10814

47108-1 05

[illegible]

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
1	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100

SUM 24.89 19.37 5.52 95414.  
( 632. ) ( 492. ) ( 140. ) ( 2701.97 )

.....

HYDROGRAPH ROUTING

ROUTED FLOWS THROUGH POWDISM RESERVOIR DAM AND SPILLWAY

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPPT	INAME	ISTAGE	IAUTO
2	1	0	0	2	0	1	0	0
ROUTING DATA								
GLOSS	CLOSS	AVG	IPRES	ISAME	IOPT	IPMP	LSTK	
0.0	0.000	0.00	1	1	0	0	0	
NSTPS NSTOL LAG AMSKK X TSK STORA ISPRAT								
1	0	0	0.000	0.000	0.000	-569.	-1	

STAGE	569.00	570.00	571.00	572.00	574.00	576.00	578.00	580.00
FLOW	0.00	61.00	178.00	337.00	724.00	1200.00	1750.00	2364.00
SURFACE AREA=	210.	242.	248.	254.	258.	263.	267.	284.
CAPACITY=	0.	226.	716.	1214.	1730.	2251.	2761.	3865.
ELEVATION=	569.	570.	572.	574.	576.	578.	580.	584.
								584.
								540.

CMEL	SPWID	COOW	EXPW	ELEVL	COOL	CARFA	FXPL
569.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

DAM DATA  
TOPEL COON EXPID DAMWID  
572.0 2.5 1.5 271.



• 00000 •

• TEAM OUTFLON IS 1645. AT TIME 44.50 HOURS

(11)

•GVF•

STATION 2

C.	400.	800.	1200.	1600.	2000.	2400.	2800.	3200.	3600.	0.	0.
30											
1.00 11											
1.30 31											
2.00 41											
2.30 51											
3.00 61											
3.30 71											
4.00 81											
4.30 91											
5.00 101											
5.30 111											
6.00 121											
6.30 131											
7.00 141											
7.30 151											
8.00 161											
8.30 171											
9.00 181											
9.30 191											
10.00 201											
10.30 211											
11.00 221											
11.30 231											
12.00 241											
12.30 251											
13.00 261											
13.30 271											
14.00 281											
14.30 291											
15.00 301											
15.30 311											
16.00 321											
16.30 331											
17.00 341											
17.30 351											
18.00 361											
18.30 371											
19.00 381											
19.30 391											
20.00 401											
20.30 411											
21.00 421											
21.30 431											
22.00 441											
22.30 451											
23.00 461											
23.30 471											
24.00 481											
24.30 491											
1.00 501											
1.30 511											
2.00 521											
2.30 531											
3.00 541											
3.30 551											
4.00 561											
4.30 571											
5.00 581											

(4)

5.30 591  
6.00 601  
6.30 611  
7.00 621  
7.30 631  
8.00 641  
8.30 651  
9.00 661  
9.30 671  
10.00 681  
10.30 691  
11.00 701  
11.30 711  
12.00 721  
12.30 731  
13.00 741  
13.30 751  
14.00 761  
14.30 771  
15.00 781  
15.30 791  
16.00 801  
16.30 811  
17.00 821  
17.30 831  
18.00 841  
18.30 851  
19.00 861  
19.30 871  
20.00 881  
20.30 891  
21.00 901  
21.30 911  
22.00 921  
22.30 931  
23.00 941  
23.30 951  
24.00 961  
24.30 971  
25.00 981  
25.30 991  
26.00 1001  
26.30 1011  
27.00 1021  
27.30 1031  
28.00 1041  
28.30 1051  
29.00 1061  
29.30 1071  
30.00 1081  
30.30 1091  
31.00 1101  
31.30 1111  
32.00 1121  
32.30 1131  
33.00 1141  
33.30 1151  
34.00 1161  
34.30 1171  
35.00 1181  
35.30 1191  
36.00 1201  
36.30 1211  
37.00 1221  
37.30 1231  
38.00 1241  
38.30 1251  
39.00 1261  
39.30 1271  
40.00 1281  
40.30 1291  
41.00 1301  
41.30 1311  
42.00 1321  
42.30 1331  
43.00 1341  
43.30 1351  
44.00 1361  
44.30 1371  
45.00 1381  
45.30 1391  
46.00 1401  
46.30 1411  
47.00 1421  
47.30 1431  
48.00 1441  
48.30 1451  
49.00 1461  
49.30 1471  
50.00 1481  
50.30 1491  
51.00 1501  
51.30 1511  
52.00 1521  
52.30 1531  
53.00 1541  
53.30 1551  
54.00 1561  
54.30 1571  
55.00 1581  
55.30 1591  
56.00 1601  
56.30 1611  
57.00 1621  
57.30 1631  
58.00 1641  
58.30 1651  
59.00 1661  
59.30 1671  
60.00 1681  
60.30 1691  
61.00 1701  
61.30 1711  
62.00 1721  
62.30 1731  
63.00 1741  
63.30 1751  
64.00 1761  
64.30 1771  
65.00 1781  
65.30 1791  
66.00 1801  
66.30 1811  
67.00 1821  
67.30 1831  
68.00 1841  
68.30 1851  
69.00 1861  
69.30 1871  
70.00 1881  
70.30 1891  
71.00 1901  
71.30 1911  
72.00 1921  
72.30 1931  
73.00 1941  
73.30 1951  
74.00 1961  
74.30 1971  
75.00 1981  
75.30 1991  
76.00 2001  
76.30 2011  
77.00 2021  
77.30 2031  
78.00 2041  
78.30 2051  
79.00 2061  
79.30 2071  
80.00 2081  
80.30 2091  
81.00 2101  
81.30 2111  
82.00 2121  
82.30 2131  
83.00 2141  
83.30 2151  
84.00 2161  
84.30 2171  
85.00 2181  
85.30 2191  
86.00 2201  
86.30 2211  
87.00 2221  
87.30 2231  
88.00 2241  
88.30 2251  
89.00 2261  
89.30 2271  
90.00 2281  
90.30 2291  
91.00 2301  
91.30 2311  
92.00 2321  
92.30 2331  
93.00 2341  
93.30 2351  
94.00 2361  
94.30 2371  
95.00 2381  
95.30 2391  
96.00 2401  
96.30 2411  
97.00 2421  
97.30 2431  
98.00 2441  
98.30 2451  
99.00 2461  
99.30 2471  
100.00 2481  
100.30 2491  
101.00 2501  
101.30 2511  
102.00 2521  
102.30 2531  
103.00 2541  
103.30 2551  
104.00 2561  
104.30 2571  
105.00 2581  
105.30 2591  
106.00 2601  
106.30 2611  
107.00 2621  
107.30 2631  
108.00 2641  
108.30 2651  
109.00 2661  
109.30 2671  
110.00 2681  
110.30 2691  
111.00 2701  
111.30 2711  
112.00 2721  
112.30 2731  
113.00 2741  
113.30 2751  
114.00 2761  
114.30 2771  
115.00 2781  
115.30 2791  
116.00 2801  
116.30 2811  
117.00 2821  
117.30 2831  
118.00 2841  
118.30 2851  
119.00 2861  
119.30 2871  
120.00 2881  
120.30 2891  
121.00 2901  
121.30 2911  
122.00 2921  
122.30 2931  
123.00 2941  
123.30 2951  
124.00 2961  
124.30 2971  
125.00 2981  
125.30 2991  
126.00 3001  
126.30 3011  
127.00 3021  
127.30 3031  
128.00 3041  
128.30 3051  
129.00 3061  
129.30 3071  
130.00 3081  
130.30 3091  
131.00 3101  
131.30 3111  
132.00 3121  
132.30 3131  
133.00 3141  
133.30 3151  
134.00 3161  
134.30 3171  
135.00 3181  
135.30 3191  
136.00 3201  
136.30 3211  
137.00 3221  
137.30 3231  
138.00 3241  
138.30 3251  
139.00 3261  
139.30 3271  
140.00 3281  
140.30 3291  
141.00 3301  
141.30 3311  
142.00 3321  
142.30 3331  
143.00 3341  
143.30 3351  
144.00 3361  
144.30 3371  
145.00 3381  
145.30 3391  
146.00 3401  
146.30 3411  
147.00 3421  
147.30 3431  
148.00 3441  
148.30 3451  
149.00 3461  
149.30 3471  
150.00 3481  
150.30 3491  
151.00 3501  
151.30 3511  
152.00 3521  
152.30 3531  
153.00 3541  
153.30 3551  
154.00 3561  
154.30 3571  
155.00 3581  
155.30 3591  
156.00 3601  
156.30 3611  
157.00 3621  
157.30 3631  
158.00 3641  
158.30 3651  
159.00 3661  
159.30 3671  
160.00 3681  
160.30 3691  
161.00 3701  
161.30 3711  
162.00 3721  
162.30 3731  
163.00 3741  
163.30 3751  
164.00 3761  
164.30 3771  
165.00 3781  
165.30 3791  
166.00 3801  
166.30 3811  
167.00 3821  
167.30 3831  
168.00 3841  
168.30 3851  
169.00 3861  
169.30 3871  
170.00 3881  
170.30 3891  
171.00 3901  
171.30 3911  
172.00 3921  
172.30 3931  
173.00 3941  
173.30 3951  
174.00 3961  
174.30 3971  
175.00 3981  
175.30 3991  
176.00 4001  
176.30 4011  
177.00 4021  
177.30 4031  
178.00 4041  
178.30 4051  
179.00 4061  
179.30 4071  
180.00 4081  
180.30 4091  
181.00 4101  
181.30 4111  
182.00 4121  
182.30 4131  
183.00 4141  
183.30 4151  
184.00 4161  
184.30 4171  
185.00 4181  
185.30 4191  
186.00 4201  
186.30 4211  
187.00 4221  
187.30 4231  
188.00 4241  
188.30 4251  
189.00 4261  
189.30 4271  
190.00 4281  
190.30 4291  
191.00 4301  
191.30 4311  
192.00 4321  
192.30 4331  
193.00 4341  
193.30 4351  
194.00 4361  
194.30 4371  
195.00 4381  
195.30 4391  
196.00 4401  
196.30 4411  
197.00 4421  
197.30 4431  
198.00 4441  
198.30 4451  
199.00 4461  
199.30 4471  
200.00 4481  
200.30 4491  
201.00 4501  
201.30 4511  
202.00 4521  
202.30 4531  
203.00 4541  
203.30 4551  
204.00 4561  
204.30 4571  
205.00 4581  
205.30 4591  
206.00 4601  
206.30 4611  
207.00 4621  
207.30 4631  
208.00 4641  
208.30 4651  
209.00 4661  
209.30 4671  
210.00 4681  
210.30 4691  
211.00 4701  
211.30 4711  
212.00 4721  
212.30 4731  
213.00 4741  
213.30 4751  
214.00 4761  
214.30 4771  
215.00 4781  
215.30 4791  
216.00 4801  
216.30 4811  
217.00 4821  
217.30 4831  
218.00 4841  
218.30 4851  
219.00 4861  
219.30 4871  
220.00 4881  
220.30 4891  
221.00 4901  
221.30 4911  
222.00 4921  
222.30 4931  
223.00 4941  
223.30 4951  
224.00 4961  
224.30 4971  
225.00 4981  
225.30 4991  
226.00 5001  
226.30 5011  
227.00 5021  
227.30 5031  
228.00 5041  
228.30 5051  
229.00 5061  
229.30 5071  
230.00 5081  
230.30 5091  
231.00 5101  
231.30 5111  
232.00 5121  
232.30 5131  
233.00 5141  
233.30 5151  
234.00 5161  
234.30 5171  
235.00 5181  
235.30 5191  
236.00 5201  
236.30 5211  
237.00 5221  
237.30 5231  
238.00 5241  
238.30 5251  
239.00 5261  
239.30 5271  
240.00 5281  
240.30 5291  
241.00 5301  
241.30 5311  
242.00 5321  
242.30 5331  
243.00 5341  
243.30 5351  
244.00 5361  
244.30 5371  
245.00 5381  
245.30 5391  
246.00 5401  
246.30 5411  
247.00 5421  
247.30 5431  
248.00 5441  
248.30 5451  
249.00 5461  
249.30 5471  
250.00 5481  
250.30 5491  
251.00 5501  
251.30 5511  
252.00 5521  
252.30 5531  
253.00 5541  
253.30 5551  
254.00 5561  
254.30 5571  
255.00 5581  
255.30 5591  
256.00 5601  
256.30 5611  
257.00 5621  
257.30 5631  
258.00 5641  
258.30 5651  
259.00 5661  
259.30 5671  
260.00 5681  
260.30 5691  
261.00 5701  
261.30 5711  
262.00 5721  
262.30 5731  
263.00 5741  
263.30 5751  
264.00 5761  
264.30 5771  
265.00 5781  
265.30 5791  
266.00 5801  
266.30 5811  
267.00 5821  
267.30 5831  
268.00 5841  
268.30 5851  
269.00 5861  
269.30 5871  
270.00 5881  
270.30 5891  
271.00 5901  
271.30 5911  
272.00 5921  
272.30 5931  
273.00 5941  
273.30 5951  
274.00 5961  
274.30 5971  
275.00 5981  
275.30 5991  
276.00 6001  
276.30 6011  
277.00 6021  
277.30 6031  
278.00 6041  
278.30 6051  
279.00 6061  
279.30 6071  
280.00 6081  
280.30 6091  
281.00 6101  
281.30 6111  
282.00 6121  
282.30 6131  
283.00 6141  
283.30 6151  
284.00 6161  
284.30 6171  
285.00 6181  
285.30 6191  
286.00 6201  
286.30 6211  
287.00 6221  
287.30 6231  
288.00 6241  
288.30 6251  
289.00 6261  
289.30 6271  
290.00 6281  
290.30 6291  
291.00 6301  
291.30 6311  
292.00 6321  
292.30 6331  
293.00 6341  
293.30 6351  
294.00 6361  
294.30 6371  
295.00 6381  
295.30 6391  
296.00 6401  
296.30 6411  
297.00 6421  
297.30 6431  
298.00 6441  
298.30 6451  
299.00 6461  
299.30 6471  
300.00 6481  
300.30 6491  
301.00 6501  
301.30 6511  
302.00 6521  
302.30 6531  
303.00 6541  
303.30 6551  
304.00 6561  
304.30 6571  
305.00 6581  
305.30 6591  
306.00 6601  
306.30 6611  
307.00 6621  
307.30 6631  
308.00 6641  
308.30 6651  
309.00 6661  
309.30 6671  
310.00 6681  
310.30 6691  
311.00 6701  
311.30 6711  
312.00 6721  
312.30 6731  
313.00 6741  
313.30 6751  
314.00 6761  
314.30 6771  
315.00 6781  
315.30 6791  
316.00 6801  
316.30 6811  
317.00 6821  
317.30 6831  
318.00 6841  
318.30 6851  
319.00 6861  
319.30 6871  
320.00 6881  
320.30 6891  
321.00 6901  
321.30 6911  
322.00 6921  
322.30 6931  
323.00 6941  
323.30 6951  
324.00 6961  
324.30 6971  
325.00 6981  
325.30 6991  
326.00 7001  
326.30 7011  
327.00 7021  
327.30 7031  
328.00 7041  
328.30 7051  
329.00 7061  
329.30 7071  
330.00 7081  
330.30 7091  
331.00 7101  
331.30 7111  
332.00 7121  
332.30 7131  
333.00 7141  
333.30 7151  
334.00 7161  
334.30 7171  
335.00 7181  
335.30 7191  
336.00 7201  
336.30 7211  
337.00 7221  
337.30 7231  
338.00 7241  
338.30 7251  
339.00 7261  
339.30 7271  
340.00 7281  
340.30 7291  
341.00 7301  
341.30 7311  
342.00 7321  
342.30 7331  
343.00 7341  
343.30 7351  
344.00 7361  
344.30 7371  
345.00 7381  
345.30 7391  
346.00 7401  
346.30 7411  
347.00 7421  
347.30 7431  
348.00 7441  
348.30 7451  
349.00 7461  
349.30 7471  
350.00 7481  
350.30 7491  
351.00 7501  
351.30 7511  
352.00 7521  
352.30 7531  
353.00 7541  
353.30 7551  
354.00 7561  
354.30 7571  
355.00 7581  
355.30 7591  
356.00 7601  
356.30 7611  
357.00 7621  
357.30 7631  
358.00 7641  
358.30 7651  
359.00 7661  
359.30 7671  
360.00 7681  
360.30 7691  
361.00 7701  
361.30 7711  
362.00 7721  
362.30 7731  
363.00 7741  
363.30 7751  
364.00 7761  
364.30 7771  
365.00 7781  
365.30 7791  
366.00 7801  
366.30 7811  
367.00 7821  
367.30 7831  
368.00 7841  
368.30 7851  
369.00 7861  
369.30 7871  
370.00 7881  
370.30 7891  
371.00 7901  
371.30 7911  
372.00 7921  
372.30 7931  
373.00 7941  
373.30 7951  
374.00 7961  
374.30 7971  
375.00 7981  
375.30 7991  
376.00 8001  
376.30 8011  
377.00 8021  
377.30 8031  
378.00 8041  
378.30 8051  
379.00 8061  
379.30 8071  
380.00 8081  
380.30 8091  
381.00 8101  
381.30 8111  
382.00 8121  
382.30 8131  
383.00 8141  
383.30 8151  
384.00 8161  
384.30 8171  
385.00 8181  
385.30 8191  
386.00 8201  
386.30 8211  
387.00 8221  
387.30 8231  
388.00 8241  
388.30 8251  
389.00 8261  
389.30 8271  
390.00 8281  
390.30 8291  
391.00 8301  
391.30 8311  
392.00 8321  
392.30 8331  
393.00 8341  
393.30 8351  
394.00 8361  
394.30 8371  
395.00 8381  
395.30 8391  
396.00 8401  
396.30 8411  
397.00 8421  
397.30 8431  
398.00 8441  
398.30 8451  
399.00 8461  
399.30 8471  
400.00 8481  
400.30 8491  
401.00 8501  
401.30 8511  
402.00 8521  
402.30 8531  
403.00 8541  
403.30 8551  
404.00 8561  
404.30 8571  
405.00 8581  
405.30 8591  
406.00 8601  
406.30 8611  
407.00 8621  
407.30 8631  
408.00 8641  
408.30 8651  
409.00 8661  
409.30 8671  
410.00 8681  
410.30 8691  
411.00 8701  
411.30 8711  
412.00 8721  
412.30 8731  
413.00 8741  
413.30 8751  
414.00 8761  
414.30 8771  
415.00 8781  
415.30 8791  
416.00 8801  
416.30 8811  
417.00 8821  
417.30 8831  
418.00 8841  
418.30 8851  
419.00 8861  
419.30 8871  
420.00 8881  
420.30 8891  
421.00 8901  
421.30 8911  
422.00 8921  
422.30 8931  
423.00 8941  
423.30 8951  
424.00 8961  
424.30 8971  
425.00 8981  
425.30 8991  
426.00 9001  
426.30 9011  
427.00 9021  
427.30 9031  
428.00 9041  
428.30 9051  
429.00 9061  
429.30 9071  
430.00 9081  
430.30 9091  
431.00 9101  
431.30 9111  
432.00 9121  
432.30 9131  
433.00 9141  
433.30 9151  
434.00 9161  
434.30 9171  
435.00 9181  
435.30 9191  
436.00 9201  
436.30 9211  
437.00 9221  
437.30 9231  
438.00 9241  
438.30 9251  
439.00 9261  
439.30 9271  
440.00 9281  
440.30 9291  
441.00 9301  
441.30 9311  
442.00 9321  
442.30 9331  
443.00 9341  
443.30 9351  
444.00 9361  
444.30 9371  
445.00 9381  
445.30 9391  
446.00 9401  
446.30 9411  
447.00 9421  
447.30 9431  
448.00 9441  
448.30 9451  
449.00 9461  
449.30 9471  
450.00 9481  
450.30 9491  
451.00 9501  
451.30 9511  
452.00 9521  
452.30 9531  
453.00 9541  
453.30 9551  
454.00 9561  
454.30 9571  
455.00 9581  
455.30 9591  
456.00 9601  
456.30 9611  
457.00 9621  
457.30 9631  
458.00 9641  
458.30 9651  
459.00 9661  
459.30 9671  
460.00 9681  
460.30 9691  
461.00 9701  
461.30 9711  
462.00 9721  
462.30 9731  
463.00 9741  
463.30 9751  
464.00 9761  
464.30 9771  
465.00 9781  
465.30 9791  
466.00 9801  
466.30 9811  
467.00 9821  
467.30 9831  
468.00 9841  
468.30 9851  
469.00 9861  
469.30 9871  
470.00 9881  
470.30 9891  
471.00 9901  
471.30 9911  
472.00 9921  
472.30 9931  
473.00 9941  
473.30 9951  
474.00 9961  
474.30 9971  
475.00 9981  
475.30 9991  
476.00 10001  
476.30 10011  
477.00 10021  
477.30 10031  
478.00 10041  
478.30 10051  
479.00 10061  
479.30 10071  
480.00 10081  
480.30 10091  
481.00 10101  
481.30 10111  
482.00 10121  
482.30 10131  
483.00 10141  
483.30 10151  
484.00 10161  
484.30 10171  
485.00 10181  
485.30 10191  
486.00 10201  
486.30 10211  
487.00 10221  
487.30 10231  
488.00 10241  
488.30 10251

\*\*\*\*\*

SUB-AREA RUNOFF COMPUTATION

CALCULATION OF INFLOW HYDROGRAPH TO CLARKVILLE POND

ISTAQ	ICOMP	IFCON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
3	0	0	0	1	0	1	0	0

HYDQ	IUMG	TAREA	SNAP	T-SOA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	1	.92	0.00	.92	0.00	0.000	0	0	0

PRECIP DATA

SPEE	PMS	R5	M12	R24	R48	R72	R96
0.60	24.50	100.00	111.00	120.00	127.00	0.00	0.00

TRSPC COMPUTED BY THE PROGRAM IS .800

LROPT	STKR	DLTKR	RTIOL	ERAIN	STKRS	RTICK	STRTL	CNSTL	ALSMX	RTIMP
0	0.00	0.80	1.00	0.00	0.00	1.00	1.00	.20	0.00	0.00

UNIT HYDROGRAPH DATA  
TP= 1.59 CP= .63 NTA= 0

RECESSION DATA  
STRTO= -1.80 GWCSN= -.05 RTIOR= 1.00

UNIT HYDROGRAPH 17 END-OF-PERIOD ORIGINATES, LAGE 1.60 HOURS, CP= .63 VOL= 1.00

33.	11.	20.	24.	18.	12.	9.	6.	3.	2.	30.
21.	15.	10.	7.	5.	3.	2.				

MO.	DA	HR.	MIN	PERIOD	RAIN	EXCS	LOSS	COMP
0	0	0	0	0	0	0	0	0

SUM 24.89 19.37 5.52 29830.  
( 632.11 492.11 140.11 844.69)

\*\*\*\*\*

COMBINE HYDROGRAPHS

COMBINE HYDROGRAPHS 2 AND 3 INFLOW TO CLARKVILLE POND

ISTAQ	ICOMP	IFCON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
4	2	0	0	1	0	1	0	0

\*\*\*\*\*

HYDROGRAPH ROUTING

COMBINED INFLOW ROUTED THROUGH CLARKVILLE POND DAM AND SPILLWAY

	ISTAQ	ICOMP	IECUV	ITAPE	JPLT	JPPT	INAME	IUSAGE	IAUTO
	5	1	0	0	<	0	1	0	0
				ROUTING DATA					
QLOSS	CROSS	AVG	IPES	ISAME	IOPT	IPMP	LSTR		
0.0	0.000	0.00	1	1	0	0	0		
	NSTPS	NSTDOL	LARS	AMSKK	X	TSK	STOREA	ISPRAT	
	1	0	0	0.000	0.000	0.000	-538.	-1	
STAGE	538.00	539.50	540.00	542.00	544.00	546.00	548.00	550.00	
FLOW	0.00	72.00	131.00	205.00	611.00	1161.00	1809.00	2547.00	3345.00
SURFACE AREA=	13.	12.	24.	30.	36.	43.	51.		
CAPACITY=	0.	31.	72.	125.	190.	268.	362.		
ELEVATION=	534.	540.	542.	544.	546.	548.	550.		
	CHFL	SPRNU	CRGM	EXPM	ELEVL	COOL	CARFA	EXPL	
	538.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
					DAM DATA				
	TOPEL	COORD	EXP.	DAMWID					
	542.0	2.5	1.5	362.					

YEAR OUTFLOW IS 2016. AT TIME 44.00 HOURS



[illegible]



[illegible]

PLAN FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS					
			RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6
			.10	.20	.30	.50	.80	1.00
HYDROGRAPH AT	1	1	708.	1417.	2125.	3542.	5668.	7085.
	( 8.05)	( 20.06)	( 40.12)	( 60.18)	( 100.31)	( 160.49)	( 200.62)	(
COULF TO	2	1	83.	214.	426.	1645.	3642.	5002.
	( 8.05)	( 2.35)	( 6.07)	( 12.07)	( 46.59)	( 103.13)	( 141.63)	(
HYDROGRAPH AT	3	1	247.	494.	741.	1235.	1975.	2469.
	( 2.38)	( 6.99)	( 13.98)	( 20.98)	( 34.96)	( 55.94)	( 69.92)	(
< COMBINED	4	1	280.	561.	865.	2016.	4571.	6353.
	( 10.44)	( 7.93)	( 15.89)	( 24.50)	( 57.09)	( 129.44)	( 179.91)	(
COULF TO	5	1	225.	477.	809.	2016.	4590.	6305.
	( 10.44)	( 6.38)	( 13.52)	( 22.92)	( 57.08)	( 129.46)	( 178.53)	(

# BOWDISH RESERVOIR DAM

## SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....		ELEVATION		INITIAL VALUE		SPILLWAY CREST		TOP OF DAM	
		STORAGE		569.00		569.00		572.00	
		OUTFLOW		0.		0.		716.	
								337.	
RATIO OF PWF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS		
.10	570.19	0.00	271.	83.	0.00	47.50	0.00		
.20	571.23	0.00	525.	214.	0.00	47.00	0.00		
.30	572.18	.18	761.	426.	5.00	46.00	0.00		
.40	573.34	1.34	1050.	1645.	13.00	44.50	0.00		
.50	574.57	2.57	1362.	3642.	21.00	44.00	0.00		
1.00	575.26	3.26	1538.	5002.	35.00	43.50	0.00		

# CLARKVILLE POND DAM

## SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....

ELEVATION  
STORAGE  
OUTFLOW

INITIAL VALUE  
538.00  
0.  
0.

SPILLWAY CREST  
538.00  
0.  
0.

TOP OF DAM  
542.00  
72.  
611.

RATIO  
OF  
PMF  
1.00  
0.80  
0.50  
0.30  
0.20  
0.10

MAXIMUM  
RESERVOIR  
W.S. ELEV  
540.10  
541.34  
542.26  
543.10  
544.30  
544.95

MAXIMUM  
STORAGE  
AC-FT  
33.  
57.  
78.  
100.  
134.  
154.

MAXIMUM  
OUTFLOW  
CFS  
225.  
477.  
809.  
2016.  
4590.  
6365.

DURATION  
OVER TOP  
HOURS  
0.00  
0.00  
2.50  
10.50  
14.50  
17.00

TIME OF  
MAX OUTFLOW  
HOURS  
43.00  
43.00  
42.50  
44.00  
43.50  
43.00

TIME OF  
FAILURE  
HOURS  
0.00  
0.00  
0.00  
0.00  
0.00  
0.00


LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB CLARKVILLE POND DAM  
SHEET NO 1 OF 7  
CALCULATED BY K. A. DATE 1/27/81  
CHECKED BY M. R. DATE 1/29/81  
SCALE \_\_\_\_\_

80-27-8

SCHEMATIC



- 1- BONDISH RESERVOIR INFLOW
- 2- " " " " ROUTED THROUGH DAM
- 3- CLARKVILLE POND INFLOW
- 4- COMBINE HYDROGRAPHS 2 AND 3
- 5- COMBINED FLOW ROUTED THROUGH CLARKVILLE POND DAM.

LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB CLARKVILLE POND DAM  
SHEET NO 2 OF 7  
CALCULATED BY K.A. DATE 1/27/81  
CHECKED BY MR DATE 1/29/81  
SCALE \_\_\_\_\_

WATERSHED AREA - BOWDISH RESERVOIR

CHEPACHET QUAD:

33 grads }  
32 " } 33 grads  $\Rightarrow$  0.08 S.M.  
33 " }

THOMPSON QUAD:

1329 grads }  
1328 grads } 1327 grads  $\Rightarrow$  3.03 S.M.

(BOWDISH RESERVOIR) TOTAL 3.11 S.M.

WATERSHED AREA - CLARKVILLE POND

THOMPSON QUAD:

405 grads }  
403 " } 404 grads  $\Rightarrow$  0.22 S.M.  
405 " }

(CLARKVILLE POND) TOTAL 0.22 S.M.

# LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB CLARKVILLE POND DAM

SHEET NO 3 OF 7

CALCULATED BY K. A. DATE 1/27/81

CHECKED BY M. R. DATE 1/28/81

SCALE


## WATER SURFACE AREAS - POWDISH RESERVOIR

ELEV. 560' (SPILLWAY): 210 Ac.

ELEV. 570': 242 Ac.

ELEV. 580': 267 Ac.

ELEV. 590': 289 Ac.




LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB CLARKVILLE POND DAM  
SHEET NO 4 OF 7  
CALCULATED BY K. A. DATE 1/27/81  
CHECKED BY M. B. DATE 1/28/81  
SCALE \_\_\_\_\_

WATER SURFACE AREAS - CLARKVILLE POND

ELEV. 538' (SPILLWAY): 13 Ac.  
ELEV. 540': 18 Ac.  
ELEV. 550': 51 Ac.





LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB CLARKVILLE POND DAM  
SHEET NO. 5 OF 7  
CALCULATED BY K. A. DATE 1/27/31  
CHECKED BY M. T. DATE 1/28/31  
SCALE \_\_\_\_\_

PRECIPITATION

U.S. WEATHER BUREAU  
TECH. PAPER No. 40

PMF - 6 HOUR

24.5 INCHES

LAG TIME (SNYDER'S)

$$t_p = C_t (L L_{CA})^{0.3}$$

BOWLISH RESERVOIR:

$$C_t = 2.0$$

$$L = 12,400' = 2.35 \text{ MI.}$$

$$L_{CA} = 3,000' = 0.57 \text{ MI.}$$

$$t_p = 2.0 [(2.35)(0.57)]^{0.3}$$

$$\underline{t_p = 2.18 \text{ HRS.}}$$

CLARKVILLE POND:

$$C_t = 2.0$$

$$L = 7200' = 1.36 \text{ MI.}$$

$$L_{CA} = 1800' = 0.34 \text{ MI.}$$

$$t_p = 2.0 [(1.36)(0.34)]^{0.3}$$


$$\underline{t_p = 1.59 \text{ HRS.}}$$

LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB CLARKVILLE POND DAM  
SHEET NO 6 OF 7  
CALCULATED BY K.A. DATE 1/27/31  
CHECKED BY M.R. DATE 1/29/31  
SCALE \_\_\_\_\_

BOWDISH RESERVOIR DAM



DAM LENGTH:  $L = \text{TOTAL LENGTH} - \text{SPILLWAY}$   
 $L = 88' + 148' + 35'$

$L = 271'$

DISCHARGE COEFFICIENT OVER DAM:

$C = 2.5$

SPILLWAY DISCHARGE:  $Q = CLH^{1.5}$

ELEV.	C	L	H	Q (CFS)
569.0	3.4	18'	0	0
570.0	3.4	18'	1	61
571.0	3.5		2	178
572.0	3.6		3	337
574.0	3.6		5	724
576.0	3.6		7	1200
578.0	3.6		9	1750
580.0	3.6	18'	11	2364

# LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB CLARKVILLE POND DAM


SHEET NO 7 OF 7

CALCULATED BY K.A. DATE 1/27/81

CHECKED BY M.P. DATE 1/29/81

SCALE

## CLARKVILLE POND DAM



DAM LENGTH:  $L = \text{TOTAL LENGTH} - \text{SPILLWAY}$   
 $L = 30' + 332' + 20'$

$L = 382'$

DISCHARGE COEFFICIENT OVER DAM:

$C = 2.5$

SPILLWAY & HEAD RACE DISCHARGE:

ELEV.	H	C	L	Q <sub>S</sub>	H	C	L	Q <sub>HR</sub>	Q <sub>TOTAL</sub>
538.0	0	2.7	27.5	0	-	-	-	-	0
539.0	1	2.6		72	-	-	-	-	72
539.5	1.5	2.6		131	0	2.6	3.5	0	131
540.0	2.0	2.6		202	0.5	2.6		3	205
542.0	4.0	2.6		572	2.5	2.8		39	611
544.0	6.0	2.6		1051	4.5	3.3		110	1161
546.0	8.0	2.6		1616	6.5	3.3		191	1807
548.0	10.0	2.6		2261	8.5	3.3		286	2547
550.0	12.0	2.6	27.5	2972	10.5	3.3	3.5	393	3365

TEST FLOOD LEVEL - 1/2 PMF

542.1 5.1 2.6 27.5 226 3.6 3.0 3.5 72 826

LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB CLARKVILLE POND DAM  
SHEET NO 1 OF 9  
CALCULATED BY K.A. DATE 1/27/81  
CHECKED BY H.D. DATE 2/18/81  
SCALE \_\_\_\_\_

DAM FAILURE ANALYSIS:

DAM LENGTH = 413'

DAM LENGTH AT MID HEIGHT = 340'

PEAK FAILURE OUTFLOW:

$$Q_{PI} = \frac{8}{27} W_b \sqrt{g} Y_o^{3/2}$$

$$W_b = 0.4 \times 340' = 136'$$

$$g = 32.2 \text{ FT/}^2$$

$$Y_o = 14.0'$$

$$Q_{PI} = \frac{8}{27} (136) \sqrt{32.2} (14.0)^{3/2}$$

$$\underline{Q_{PI} = 11,978 \text{ CFS}}$$


STORAGE (ASSUMED): 165 AC.-FT.

# LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB CLARKVILLE POND DAM  
SHEET NO R OF 7  
CALCULATED BY G.B. DATE 1/28/31  
CHECKED BY K.A. DATE 2/17/31  
SCALE \_\_\_\_\_

## SECTION #1 - CLARKVILLE POND STA 1+70



$K = 1.02$   
 $S = .040$   
 $L = 170'$

<u>Q</u>	<u>H</u>	<u>W/P</u>	<u>E</u>	<u>V</u>	<u>Q</u>
100	10	100	100	100	100
200	20	200	200	200	200
300	30	300	300	300	300
400	40	400	400	400	400
500	50	500	500	500	500
600	60	600	600	600	600
700	70	700	700	700	700
800	80	800	800	800	800
900	90	900	900	900	900
1000	100	1000	1000	1000	1000

# LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB

SHEET NO

CALCULATED BY


CHECKED BY

SCALE

OF

DATE

DATE




# LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB CLARKVILLE POND DAM  
SHEET NO 4 OF 9  
CALCULATED BY G.E. DATE 1/20/81  
CHECKED BY K.A. DATE 2/18/81  
SCALE \_\_\_\_\_

## SECTION # 2 - CLARKVILLE POND DAM STA 9+70




<u>H</u>	<u>H</u>	<u>WD</u>	<u>R</u>	<u>V</u>	<u>Q</u>
1	500	350	2.0	2.1	1386
6	550	400	2.2	2.7	3402
8	5800	450	4.4	3.6	3332
11	5700	500	4.9	3.8	3002
12	5600	500	5.0	3.8	3002

# LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB CLARK VILLAGE SHEET NO. 5 OF 9  
CALCULATED BY ATC DATE 1/14/81  
CHECKED BY K.A. DATE 2/13/81  
SCALE \_\_\_\_\_





# LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB CLARKVILLE POND DAM

SHEET NO 6 OF 9

CALCULATED BY MR DATE 1/28/80

CHECKED BY L.A. DATE 2/18/81

SCALE


STA 22+70

Station	Top of Dam	Top of Embankment	Top of Roadway	Bottom of Roadway	Bottom of Embankment	Bottom of Dam	Notes
22+70	100.00	98.00	96.00	94.00	92.00	90.00	
22+75	100.00	98.00	96.00	94.00	92.00	90.00	
22+80	100.00	98.00	96.00	94.00	92.00	90.00	
22+85	100.00	98.00	96.00	94.00	92.00	90.00	
22+90	100.00	98.00	96.00	94.00	92.00	90.00	
22+95	100.00	98.00	96.00	94.00	92.00	90.00	
23+00	100.00	98.00	96.00	94.00	92.00	90.00	
23+05	100.00	98.00	96.00	94.00	92.00	90.00	
23+10	100.00	98.00	96.00	94.00	92.00	90.00	
23+15	100.00	98.00	96.00	94.00	92.00	90.00	
23+20	100.00	98.00	96.00	94.00	92.00	90.00	
23+25	100.00	98.00	96.00	94.00	92.00	90.00	
23+30	100.00	98.00	96.00	94.00	92.00	90.00	
23+35	100.00	98.00	96.00	94.00	92.00	90.00	
23+40	100.00	98.00	96.00	94.00	92.00	90.00	
23+45	100.00	98.00	96.00	94.00	92.00	90.00	
23+50	100.00	98.00	96.00	94.00	92.00	90.00	
23+55	100.00	98.00	96.00	94.00	92.00	90.00	
23+60	100.00	98.00	96.00	94.00	92.00	90.00	
23+65	100.00	98.00	96.00	94.00	92.00	90.00	
23+70	100.00	98.00	96.00	94.00	92.00	90.00	

# LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB CLARK VILLAGE OF 7  
SHEET NO. 1 OF 7  
CALCULATED BY ME DATE 1/17/51  
CHECKED BY KA DATE 2/18/51  
SCALE \_\_\_\_\_




# LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB CLARKVILLE ROAD DRAIN  
SHEET NO 8 OF 9  
CALCULATED BY 11/1 DATE 1/12/31  
CHECKED BY K.L. DATE 2/10/31  
SCALE \_\_\_\_\_

SECTION 4

STA 37+70



SCALE:  
HOR. 1" = 200'  
VERT. 1" = 10'

S = 2.05  
H = 2.02  
L = 18.00


	1	2	3	4	5
1	400	2.0	2.0	2.0	2.0
2	380	2.0	2.0	2.0	2.0
3	375	2.0	3.5	9.6	8400

# LENARD & DILAJ ENGINEERING, INC.

1066 Storrs Road  
STORRS, CONNECTICUT 06268  
(203) 429-7308

JOB CLARKVILLE FWD DRAIN  
SHEET NO 9 OF 11  
CALCULATED BY MZ DATE 1/27/31  
CHECKED BY K.A. DATE 2/13/31  
SCALE \_\_\_\_\_

## SECTION 4



2.5 - 3.5

4 - 4.4

4.5 - 7.0

7.0 - 8.0

2.5 - 3.5


2.5 - 3.5

4.0 - 4.4

4.5 - 7.0

7.0 - 8.0

2.5 - 3.5



## **APPENDIX E**

INFORMATION AS CONTAINED IN THE  
NATIONAL INVENTORY OF DAMS

NOT AVAILABLE AT THIS TIME

**END**

**FILMED**

**8-85**

**DTIC**